



Kenilworth Parkside RC Lead in Water Test Results

FY21 Filter Test

| Less than 5ppb - Devices requiring no remediation | | | | | | | | | | | |
|---------------------------------------------------|-----------------------|------------------------|-------|---------------|-----------------------------------------|---------------------|---------------|-------------------------|----------------------------------|-------------------------|----------------------------------|
| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
| WS- 007000 | 6/12/2020 | 6/12/2021 | 1 | Bottle Filler | In hallway adjacent to fitness room 106 | WF-06122020-007000 | 4/16/2021 | FT-FY21-042021-007000-A | <1 | FT-FY21-042021-007000-B | <1 |
| WS- 007001 | 6/12/2020 | 6/12/2021 | 1 | Cooler | In hallway adjacent to fitness room 106 | WF-06122020-007001 | 4/16/2021 | FT-FY21-042021-007001-A | <1 | FT-FY21-042021-007001-B | <1 |

Food Prep Sink

| Less than 5ppb - Devices requiring no remediation | | | | | | | | | | | |
|---------------------------------------------------|-----------------------|------------------------|-------|----------------|-----------------------------------------------|---------------------|---------------|-------------------------|----------------------------------|-------------------------|----------------------------------|
| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
| WS- 007005 | 2/9/2021 | 2/9/2022 | 1 | Food Prep Sink | In 114 kitchen second clockwise from entrance | WF-02092021-007005 | 4/16/2021 | FT-FY21-042021-007005-A | <1 | FT-FY21-042021-007005-B | <1 |